



LAMBORGHINI MIRROR
WIRING CONNECTOR
VIEWED FROM SWITCH SIDE
(CONNECTOR PINS EXIT AT
FAR SIDE OF THIS VIEW)


PLEASE NOTE: PIN NUMBER
ASSIGNMENTS ARE REFERENCE
ONLY - LAMBORGHINI
DID NOT NUMBER PINS



NOTE: WIRE TERMINAL #4
IS NOT USED ON MIRRORS
WITHOUT HEATERS.
SATURN PART NUMBER
22664402 APPEARS TO BE
AN IDENTICAL SWITCH.



LEFT OUTSIDE MIRROR



RIGHT OUTSIDE MIRROR

CHECK MIRROR MOTOR MOTION BEFORE DETERMINING WIRE CONNECTIONS.
IF ANY MIRROR MOVES THE WRONG DIRECTION, PER SWITCH POSITION,
RE-CONNECT THAT MOTOR BY SWITCHING ITS TWO WIRES FOR EACH OTHER AT
THAT MOTOR'S LOCATION IN ITS HOUSING. DON'T RE-WIRE AT THE SWITCH.